DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-021948

Address: 333 Burma Road **Date Inspected:** 12-Mar-2011

City: Oakland, CA 94607

OSM Arrival Time: 1500 **Project Name:** SAS Superstructure **OSM Departure Time:** 300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** ShangHai, China

CWI Name: Sha Zhi **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

Summary of Items Observed: On this date Caltrans OSM Quality Assurance(QA) Inspector, DJ Shin was present during the times noted above for observations relative to the work being performed.

Bay 14

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is identified as Zhu Lin.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specifications

(WPS). Listed below are the locations that were identified by this QA inspector.

Components: 13AW PCMK: SEG3013K-162

Welder: 067876

WPS-B-T-2233-ESAB

PCMK: SEG3013H-058

Welder: 203871

WPS-B-T-2233-ESAB

PCMK: SEG3013R-006

Welder: 066421

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

WPS-B-T-2232-ESAB

Components: 14W

PCMK: SEG3020AC-076,077 Welder: 045175, 067949 WPS-B-T-2133-ESAB

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Shield Metal Arc Welding (SMAW) process.

ZPMC OC is identified as Zhu Lin.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector

Components: 13AW

PCMK: SEG3013AA-118

Welder: 066038

WPS-B-P-2214-TC-U4b-FCM-1

PCMK: SEG3013AA-116

Welder: 047864

WPS-B-P-2214-TC-U4b-FCM-1

This QA inspector performed Ultrasonic Testing (UT) of approximately 10 % of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member(s) is/are identified as follows; Anchor Plate Bearing Block on item number 1~24, of NWIT tracker document # 08530,

This QA inspector performed Magnetic Particle Testing (MT) and Visual Inspection (VT) of approximately 15 % of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member(s) is/are identified as follows; Anchor plate bearing block on item number 2 and 3 of NWIT tracker document # 08527, and SEG 3007AY/SEG3007X on item number 3 and 4 of NWIT tracker document # 08526.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By:	Shin,DJ	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer